



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: December 17, 2008

Reviewed: CP

Mine Name: Red Summit Mine	Permit Number: S/043/0031
Operator Name: Pabco Building Products LLC	Inspection Date: 12/04/2008
Inspector(s): Brett Gregory for Leslie Heppler	Time: 4:00 pm
Other Participants: None	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$20,700

Permit fee: Current.

Purpose of Inspection: Routine annual inspection.

Inspection Summary:

12. Operator has not yet started mining on this permit. Old disturbance as photographed is historic and predated this operation. GPS data was gathered.

(Photos attached).

Conclusions and Recommendations: DOGM will continue to monitor this site.

Inspector's Signature

BG:vs

cc: Alfred Muller

O:\M043-Summit\S0430031-RedSummit\inspections\insp-12042008.doc



Center of site.



The road encircles the previously disturbed area.



Fence and disturbance.



Main highwall for mining



Site



Sagebrush vegetation



Garbage to be removed



Mining area on the east side of the fence